

# Introduction to Basic Motor Control System by NM1120



**2019/May**



# Demo Purpose

## ➤ Easily & Rapidly Getting Start for Motor Application

- Provide demo system for refer-design


## ➤ Motor Drive System

- Elementary S/W flow
- Refer H/W circuit




## ➤ Friendly GUI Interface Linking PC and System Board through UART(COM port)

- User can easily demo motor behavior



# Demo System



# Overview

---

- **Demo how to use NM1120 to implement a basic motor drive system with**
  - Hall + FOC + 2-shunt R
  - Hall + FOC + 1-shunt R
  - Hall + Six step square wave control
    - Duty open loop
    - Speed close loop
- **Customer may refer this demo system to develop own specific system.**

# Demo Function

---

- ✓ **Demo NM1120 MCU basic setting**
  - Initialize MCU
  - Timer
  - Interrupt
  - ECAP (Enhance Capture Timer/Counter)
  - Complementary PWM0~5 setting
  - 12-bit 2-S/H ADC
  - PGA (Programmable Gain Amplifier)
  - ACMP (Analog Comparator)
- ✓ **Basic PI control (Proportional and Integral control) for speed and current control**
- ✓ **Basic FOC + SVPWM (Library)**


# Demo Function

---

- ✓ **6-Step square wave control**
- ✓ **Basic motor speed estimation by ECAP**
- ✓ **System control mode**
  - VSP control mode : External VR to turn on/off the motor and adjust speed
  - UART control mode : Set command from PC to MCU through UART protocol.
- ✓ **Control mode selection :**
  - VSP control mode : Rotate VR to make VSP initial voltage  $< 2.5V$  before power on .
  - UART control mode : Rotate VR to make VSP initial voltage  $> 2.5V$  before power on .


# Speed Control by FOC

- ▶ Demo System : Hall + FOC
- ▶ Control mode : 2R / 1R (R : current shunt resistance)




# PWM Duty Control by 6-Step

- ▶ Demo System : Hall + Six Step square wave control
- ▶ Control mode : Duty open loop




# Speed Control by 6-Step

- ▶ Demo System : Hall + Six Step square wave control
- ▶ Control mode : Speed close loop




# FOC by Software Library

- ▶ FOC: Field Oriented Control, 磁場導向控制
- ▶ Vector Control: 向量控制, 矢量控制
- ▶ a-b-c stationary frame
- ▶  $\alpha$ - $\beta$  stationary frame
- ▶ d-q rotating frame



# FOC control block




# FOC Function Call

---

- ▶ void **luvw\_to\_Idq**(AMotor\* Motor, int32 sin, int32 cos)
  - Do Clark Transfer: Transfer  $I_u/v/w$  to  $I_{\alpha/\beta}$
  - Do Park Transfer: Transfer  $I_{\alpha/\beta}$  to  $I_{d/q}$
- ▶ void **Vdq\_to\_SVPWM**(AMotor\* Motor, EPWM\_T\* epwm, int32 pwm\_full\_scale, int32 pwm\_max\_duty, int32 sin, int32 cos)
  - Do Inv\_Park Transfer: Transfer  $V_{d/q}$  to  $V_{\alpha/\beta}$
  - Do Modified Inv\_Clark Transfer: Transfer  $V_{\alpha/\beta}$  to  $V_{refx/y/z}$
  - Do SVPWM calculation to produce Duty0/2/4
  - Update the duty to EPWM->CMPDAT[0/2/4]

# Phase Current Detection by ADC

- ▶ 2-shunt R :  $I_u$  /  $I_v$  from external two OP
- ▶ 1-shunt R :  $I_u$  /  $I_v$  /  $I_w$  through internal PGA



# Six Step square wave control

- ▶ Sequentially output PWM according with Hall-State.
- ▶ Do phase change by setting EPWM Phase Change Register (EPWM\_PHCHG).

## Forward

STAGE FW	HALL STATES	HW PB2	HV PB1	HU PB0	Exciting phase	Gate signal					
						U_H	U_L	V_H	V_L	W_H	W_L
1	5	1	0	1	u→w	PWM	0	0	0	0	1
2	1	0	0	1	v→w	0	0	PWM	0	0	1
3	3	0	1	1	v→u	0	1	PWM	0	0	0
4	2	0	1	0	w→u	0	1	0	0	PWM	0
5	6	1	1	0	w→v	0	0	0	1	PWM	0
6	4	1	0	0	u→v	PWM	0	0	1	0	0

## Reverse

STAGE RW	HALL STATES	HW PB2	HV PB1	HU PB0	Exciting phase	Gate signal					
						U_H	U_L	V_H	V_L	W_H	W_L
1	3	0	1	1	u→v	PWM	0	0	1	0	0
2	1	0	0	1	w→v	0	0	0	1	PWM	0
3	5	1	0	1	w→u	0	1	0	0	PWM	0
4	4	1	0	0	v→u	0	1	PWM	0	0	0
5	6	1	1	0	v→w	0	0	PWM	0	0	1
6	2	0	1	0	u→w	PWM	0	0	0	0	1

# Six Step square wave Function Call

---

- ▶ void **SIX\_STEP\_CHANGE\_PHASE\_FW**(void)
  - Do phase change function for rotor forward
  - Using EPWM Phase Change Register (EPWM\_PHCHG) to change phase
  
- ▶ void **SIX\_STEP\_CHANGE\_PHASE\_RW**(void)
  - Do phase change function for rotor reverse
  - Using EPWM Phase Change Register (EPWM\_PHCHG) to change phase

# Motor Variable Structure

```
typedef struct tag_Motor
```

```
{
```

AMotorSpec	spec;	馬達系統基本規格, ex: PWM 頻率
AMotorInfo	info;	即時的data, ex: lu, lv, lw, rotor_speed
AMotorCommand	cmd;	馬達驅動的命令, ex:轉子速度命令rpm
AMotorController	ctrl;	控制器的最大限制值
AMotorSym	sym;	系統資訊, ex: 過流錯誤回報資料
AMotorOther	other;	一些系統程式執行時需要的變數或flag

```
} AMotor;
```

# PI Controller Variable Structure

---

```
typedef struct
```

```
{
```


```
    INT32  e1;           Error = cmd – info, Q15 format
```

```
    INT32  ui_31;       Accumulated integrator, Q31 format
```

```
    INT32  kp_15,ki_15; Parameters of Kp & Ki, Q31 format
```


```
}PICs;
```

# Key Variables




# Flow Chart of main.c

## ► Main program to initialize MCU and system




# Flow Chart of TMR0\_INT (for FOC)

- ▶ Timer0 INT for system timer handles the user interface and speed control




# Flow Chart of TMR0\_INT (for Six step)

- ▶ Timer0 INT for system timer handles the user interface and speed control




# Flow Chart of EADC\_INT (for 2R)

## ▶ EADC INT: for current control and FOC




# Flow Chart of EPWM\_INT (for 1R)

## ▶ EPWM INT: for current control and FOC (1R)




# Flow Chart of ECAP\_INT(for FOC)

- ▶ ECAP INT for capturing hall sensor signals to update the hall angle and rotor speed




# Flow Chart of ECAP\_INT(for Six step)

- ▶ ECAP INT for capturing hall sensor signals to update the hall angle and rotor speed




# Flow Chart of BRAKE0\_INT

- ▶ BRAKE0 INT to STOP PWM and turn off MOS when over current




# Flow Chart of UART\_INT

## ▶ UART INT for data decoding and returning data to the host




# Pin Configure vs Circuit (I)



- ✓ **PWM output (6 pin) by EPWM**
  - (PWM5~PWM0) = (PA5~PA0)
- ✓ **Direction command from RUN switch (1 pin) by GPIO**
  - PC4: read the state of RUN switch
- ✓ **Light LED (1 pin) by GPIO**
  - PD4: control LED on/off
- ✓ **UART port (2 pin) by USCI-UART0**
  - UART0\_RXD = PD6
  - UART0\_TXD = PD5
- ✓ **Nu-Link ICE port by SWD**
  - ICE\_DAT = PD2
  - ICE\_CLK = PD1
- ✓ **(Optional) DAC module by SPI0**
  - SPI0\_MOSI = PD2
  - SPI0\_CLK = PD1
  - CS = PD3 (GPIO mode)

# Pin Configure vs Circuit (II)



The R31 in LVMDM must be removed if PGA is used

- ✓ **Hall sensor (3 pins) by ECAP**
  - (Hw, Hv, Hu) = (PB2, PB1, PB0) = (ECAP2, ECAP1, ECAP0)
- ✓ **Phase current feedback (2 pins) by ADC**
  - Iu: ADC0\_CH3 = PC0
  - Iv: ADC1\_CH0 = PB4
- ✓ **Total current amplify(2 pin) by PGA**
  - IRSum = PGA\_I = PB3
  - Set PGA gain = 5
  - PGA\_O = PC3 to I\_OC through RC filter
- ✓ **Over current detect (1 pin) by ACMP0**
  - I\_OC = ACMP0\_P3 = PC1
- ✓ **Speed command from VR (1 pin) by ADC**
  - Speed = ADC1\_CH2 = PC2

# Pin Configure in Demo System (I)

- ✓ **Hall sensor (3 pins) by ECAP**
  - (Hw, Hv, Hu) = (PB2, PB1, PB0) = (ECAP2, ECAP1, ECAP0)
- ✓ **Phase current feedback (2 pins) by ADC (for 2-shunt R)**
  - Iu: ADC0\_CH3 = PC0
  - Iv: ADC1\_CH0 = PB4
- ✓ **Total current amplify (2 pin) by PGA**
  - IRSum = PGA\_I = PB3
  - Set PGA gain = 5
  - PGA\_O = PC3 → RC filter → I\_OC = ACMP0\_P3
  - Internally PGA\_O to ADC for phase current measurement (1-shunt R)
- ✓ **Over current detect (1 pin) by ACMP0**
  - I\_OC = ACMP0\_P3 = PC1
- ✓ **Speed command from VR (1 pin) by ADC**
  - Speed = ADC1\_CH2 = PC2

# Pin Configure in Demo System (II)

---

- ✓ PWM output (6 pin) by EPWM
  - (PWM5~PWM0) = (PA5~PA0)
- ✓ Direction command from RUN switch (1 pin) by GPIO
  - PC4: read the state of RUN switch
- ✓ Light LED (1 pin) by GPIO
  - PD4: control LED on/off
- ✓ UART port (2 pin) by USCI-UART0
  - UART0\_RXD = PD6
  - UART0\_TXD = PD5
- ✓ Nu-Link ICE port by SWD
  - ICE\_DAT = PD2
  - ICE\_CLK = PD1


# Pin Configure in Demo System (III)

---

- ✓ (Optional) DAC module by SPI0
  - SPI0\_MOSI = PD2
  - SPI0\_CLK = PD1
  - CS = PD3 (GPIO mode)

# Hall signal correction

- ▶ The correspondence between BEMF & hall signal as bellow
- ▶ User can correct with line or phase voltage (example: Type 1)




# Hall signal correction

---

- ▶ User can select hall type 0 or type 1 in the example code
- ▶ **Hall type 0** mean the **falling** edge of hall signal align phase voltage peak
- ▶ **Hall type 1** mean the **rising** edge of hall signal align phase voltage peak

# Type0 : Hall and BEMF for RW



Define the 1<sup>st</sup> hall state right after the rising edge at IC0 as "HALL\_STATE1\_RW"

Hall Sensor (W,V,U) =  
Input Capture (IC2, IC1, IC0) =  
I/O Port (PB2, PB1, PB0) =  
3, 1, 5, 4, 6, 2...for CCW

```
#define HALL_STATE1_RW 3
#define HALL_STATE2_RW 1
#define HALL_STATE3_RW 5
#define HALL_STATE4_RW 4
#define HALL_STATE5_RW 6
#define HALL_STATE6_RW 2
```

```
#define HALL_STATE1_R_ANGLE
1024*(-90+0)/360
```

```
#define HALL_STATE2_R_ANGLE
1024*(-150+0)/360
```

```
#define HALL_STATE3_R_ANGLE
1024*(-210+0)/360
```

```
#define HALL_STATE4_R_ANGLE
1024*(-270+0)/360
```


```
#define HALL_STATE5_R_ANGLE
1024*(-330+0)/360
```

```
#define HALL_STATE6_R_ANGLE
1024*(-30+0)/360
```

# Type0 : Hall and BEMF for FW

Hall Type 0

Forward Running (FW)



Define the 1<sup>st</sup> hall state right after the rising edge at IC0 as "HALL\_STATE1\_FW"

Hall Sensor (W,V,U) =  
Input Capture (IC2, IC1, IC0) =  
I/O Port (PB2, PB1, PB0) =  
5, 1, 3, 2, 6, 4...for FW

```
#define HALL_STATE1_FW 5
#define HALL_STATE2_FW 1
#define HALL_STATE3_FW 3
#define HALL_STATE4_FW 2
#define HALL_STATE5_FW 6
#define HALL_STATE6_FW 4
```

```
#define HALL_STATE1_F_ANGLE
1024*(270+0)/360 + SHIFT_180
```

```
#define HALL_STATE2_F_ANGLE
1024*(330+0)/360 + SHIFT_180
```


```
#define HALL_STATE3_F_ANGLE
1024*(30+0)/360 + SHIFT_180
```

```
#define HALL_STATE4_F_ANGLE
1024*(90+0)/360 + SHIFT_180
```

```
#define HALL_STATE5_F_ANGLE
1024*(150+0)/360 + SHIFT_180
```

```
#define HALL_STATE6_F_ANGLE
1024*(210+0)/360 + SHIFT_180
```

# Type1 : Hall and BEMF for FW



Define the 1<sup>st</sup> hall state right after the rising edge at IC0 as "HALL\_STATE1\_FW"

Hall Sensor (W,V,U) =  
Input Capture (IC2, IC1, IC0) =  
I/O Port (PB2, PB1, PB0) =  
5, 1, 3, 2, 6, 4...for FW


```
#define HALL_STATE1_FW 5
#define HALL_STATE2_FW 1
#define HALL_STATE3_FW 3
#define HALL_STATE4_FW 2
#define HALL_STATE5_FW 6
#define HALL_STATE6_FW 4
```

```
#define HALL_STATE1_F_ANGLE
1024*(90+0)/360 + SHIFT_180
#define HALL_STATE2_F_ANGLE
1024*(150+0)/360 + SHIFT_180
#define HALL_STATE3_F_ANGLE
1024*(210+0)/360 + SHIFT_180
#define HALL_STATE4_F_ANGLE
1024*(270+0)/360 + SHIFT_180
#define HALL_STATE5_F_ANGLE
1024*(330+0)/360 + SHIFT_180
#define HALL_STATE6_F_ANGLE
1024*(30+0)/360 + SHIFT_180
```

# Type1 : Hall and BEMF for RW

Hall Type 1

Reverse Running (RW)



Define the 1<sup>st</sup> hall state right after the rising edge at IC0 as "HALL\_STATE1\_RW"

Hall Sensor (W,V,U) =  
Input Capture (IC2, IC1, IC0) =  
I/O Port (PB2, PB1, PB0) =  
3, 1, 5, 4, 6, 2...for CCW

```
#define HALL_STATE1_RW 3
#define HALL_STATE2_RW 1
#define HALL_STATE3_RW 5
#define HALL_STATE4_RW 4
#define HALL_STATE5_RW 6
#define HALL_STATE6_RW 2
```

```
#define HALL_STATE1_R_ANGLE
1024*(-270+0)/360
```

```
#define HALL_STATE2_R_ANGLE
1024*(-330+0)/360
```

```
#define HALL_STATE3_R_ANGLE
1024*(-30+0)/360
```

```
#define HALL_STATE4_R_ANGLE
1024*(-90+0)/360
```

```
#define HALL_STATE5_R_ANGLE
1024*(-150+0)/360
```

```
#define HALL_STATE6_R_ANGLE
1024*(-210+0)/360
```

**END**